

Vista Tower, Stevenage | Fire safety situation report

Update 30 September 2020

The cladding at the building comprises UPVC curtain glazing with UPVC infill panels with a polystyrene core. The landlord has submitted an application to the Government's Building Safety Fund and has appointed a surveying company to oversee the work required. It has become evident that some internal compartmentation work may be required at the building which is being further investigated.