+INSIZE+

HORIZONTAL PROFILE PROJECTORS











ISP-A7000E



digital readout of ISP-A7000E

- touch buttons
- USB data output to Excel and CAD
- show diagram directly







software CD (included, only for ISP-A7000E)



lone



demo sample (need rotary table)



300mm calibration scale (check magnification accuracy together with 50mm reading scale or calibrate measuring accuracy)


OPTIONAL ACCESSORY



V-block with clamp



vise



Ø300mm overlay chart (protractor with 1° graduation, radius with 1mm increment)



rotary table



printer (only for ISP-A7000E)



50mm reading scale (check magnification accuracy)

To be continued



Continued from previous page

SPECIFICATION

SPECIFICATION Code		ISP-W4025			ISP-A7000E			
Edge detector		not included			included			
Lens	magnification	5X (optional)	10X (standard)	20X (op	tional)	50X (optional)	100X (optional)	
	view field	Ø80mm	Ø40mm	Ø20mm		Ø8mm	Ø4mm	
	working distance	93.7mm	103.9mm	95.1mm		65.7mm	35mm	
Magnification	<u> </u>	±0.08%						
Image		erect image						
Projector screen		diameter: Ø400mm						
		rotation range: 0°~360°, resolution: 1' or 0.01°						
		reference lines: cross-hairs						
	metal stage size	450×200mm						
	turning range	±15°						
		range: 250×150mm						
Stage	X-Z stage travel	resolution: 0.5µm						
		accuracy: (4+L/25)µm L is the measuring length in mm						
	Y (focus) travel range	100mm						
	max. load capacity	50kg						
Illumination	Illumination		contour illumination: 24V/150W halogen lamp, brightness is adjustable					
		surface illumination: 12V/150W halogen lamp(with 2 fibers), position is adjustable						
	display	X-Z stage travel, screen rotation						
	output	RS232C			RS232C, USB (data output to Excel and CAD)			
	function	x measure	coordinate of point		()	measure coordinate	of point	
		measure coordinate of line		measure coordinate of line				
Data processing unit		radius of	center coordinate, circle with three poir	nts	measure center coordinate, radius of circle with three points		three points	
		measure distance between two objects			measure distance between two objects			
		measure or two lin	angle with four point les	ts		measure angle with or two lines	four points	
		set origin	of coordinate			coordinate transform	1	
		coordinate transform			choose measurement object automatically according to the selective point and display the result			
		set midp	oint of coordinate		Sciective point and display the result			
	advanced function				programming for batch measurements			
Power supply		110/220V, 50/60Hz						
Dimension (L×W×H)		1215×646×1210mm						
Weight		240kg						

STANDARD DELIVERY

VIAIDARD DELIVERY				
Main unit	1 pc			
10X lens	1 pc			
Overlay chart clip	4 pcs			
Foot-switch	1 pc			
Anti-dust cover	1 pc			
USB cable and software (only for ISP-A7000E)	1 pc			

OPTIONAL ACCESSORY

5X lens	ISP-W4025-LENS5X
20X lens	ISP-W4025-LENS20X
50X lens	ISP-W4025-LENS50X
100X lens	ISP-W4025-LENS100X
Ø300mm overlay chart	ISP-A3000-CHART
50mm reading scale	ISP-A3000-SCALE50

300mm calibration scale	ISP-A3000-RULE		
Demo sample	ISP-A3000-DEMO		
V-block with clamp	ISP-A1000-VBLOCK		
Rotary table	ISP-A3000-RTABLE		
Vice	ISP-A3000-VISE		
Printer (only for ISP-A7000E)	ISP-A3000-PRINTER		