







O Heap & Son (Derby) Ltd

Chase Fire

Kent Fire

Activity: Use of Mobile Elevating Work Platforms

Assessors Name:	Chris Ogden	5. Extreme	5 (LOW)	10 (MED)	15 (MED)	20 (HIGH)	25 (HIGH)				
		4. Major	4 (LOW)	8 (MED)	12 (MED)	16 (MED)	20 (HIGH)				
Assessors Signature:	Chris Ogden	3. Minor	3 (LOW)	6 (MED)	9 (MED)	12 (MED)	15 (MED)				
		2. Limited	2 (LOW)	4 (LOW)	6 (MED)	8 (MED)	10 (MED)				
Assessment Date:	01/01/2019	1. Trivial	1 (LOW)	2 (LOW)	3 (LOW)	4 (LOW)	5 (LOW)				
			1. Unlikely	2. Rarely	3.Occasional	4. Frequent	5.Inevitable				
Contract Title:	Various client premises throughout the UK.	RATING	RATING				2 years				
EFFECTED PERSONS:		HIGH RIS	SK .	Intolerable - Do not start work							
Visitors X	Employees X Public X	MED RISI	MED RISK		Tolerable - Reduce ALARP. Review bi-annually/change.						
Others (specify)	Contractors X	LOW RIS	K	Tolerable - I	Tolerable - Monitor. Review bi-annually/change.						

No.	Hazard/Aspect	H&S Consequence	Pre-	100	ntro	Control Measures to be Employed	Fin	nal R	lisk
	Hazardous Event	Environmental Impact	R	atir	ng		R	Ratin	g
				xS = Ris					
1	MEWP Collapsing	death.	2	5	10	servicing and inspection by by a competent person (at six-month intervals). Restrict non-essential persons from the works area by the use of barriers and signage.	1	5	5
		Severe injury including death. Property damage.	2	5	10		1	5	5









O Heap & Son (Derby) Ltd

Chase Fire

Key Fire Kent Fire

5		Electrocution/Burns/ Death	2	5	10	Maintain a safe distance from overhead electrical cables. No part of any machine should be closer than 15 metres to any overhead line on steel pylons (9 metres if on a wooden or steel pole) unless by agreement with the electricity company. Supervisor/Manager/Client to carry out checks to ensure that the operative is using controls. Regular toolbox talks will be delivered (documented and recorded).	1	5	5)
4	Person trapped between carrier and a fixed structure Failure of MEWP in elevated position	Severe injury including fractures, potential death		5	10	Check for overhead crushing or contact hazards. Ensure that operators are appropriately trained (IPAF holder) and are familiar with the operation of the equipment selected. Utilise a Banksman for all operations and establish good communication between the operator and Banksman. Ensure adequate supervision. Ensure that a suitable rescue plan is in place, operatives are trained in rescue procedures.	1	5	5
	carrier, Carrier caught on fixed structure, Operator error) Persons thrown from carrier.	Severe injury including fractures, potential death		5	10	of MEWP cannot protrude into roads or other transport routes (alternately effect a temporary road closure). Consider the range of movement and the anticipated load, e.g. people and tools. Ensure loads are kept within safe limits. A MEWP must not be used as a crane. Check for overhead crushing or contact hazards. Ensure operators are appropriately trained (IPAF qualification holder) and is familiar with the operation of the equipment selected. Establish limits for safe operation. Utilise a Banksman for all operations. Where appropriate operate a permit to work system. Travelling with the carrier or boom extended should be avoided Ensure that persons within the carrier wear appropriate work restraint or fall protection equipment (except where working near water, then a life jacket should be worn). When selecting appropriate equipment ensure that the rating of the anchor points on the MEWP, the height of working and the presence of projections that a person could strike during a fall are are all taken into account. Also ensure that a suitable rescue plan is in place and operatives are aware of such a plan. Users of protective equipment should be trained in its use and the procedures for periodic inspection, maintenance and storage of it.	1	5	0.