

Date: 10/10/2024

TO: Dan Shouldice

883 Craig Road

Oxford Mills, ON. K0G 1S0

FROM: Albert's Liquid Waste

RE: Septic Inspection

BCIN # 40837

COMMENTS:

Upon inspection of 883 Craig Road, the septic tank was found to be a double chambered concrete tank approximately 800 gallons (3600 litres) in size. After a visual inspection of the septic tank, it looked to be in good structural condition. Both the inlet and outlet baffles were in place. The center partition wall was in place and showed slight signs of erosion. Slight decay was also noticed around the outlet pipe of the tank. A flow test was performed where the weeping bed took 30 minutes of water flow in, with no backflow to the tank observed at any time during the test. The tile bed surface area both before and after the flow test was firm and dry and showed no wet or spongy areas or signs of effluent breakout to the surface.

Overall, the system appears to be operating properly at this time of inspection.

Inspection result: **PASS**

Sincerely,

Ryan Miller

Ryan Miller

Albert's Liquid Waste

ALBERT'S LIQUID WASTE 295 Davis Road RR3 Merrickville ON K0G 1N0 613.258.7896

INSPECTION

