

WETT RECOMMENDED INSPECTION CHECKLIST

Requested by: Dale Kirkpatrick	Inspection location: O Same as requested or:
Address: 7645 Settlers Way Ottawa, ON	Address:
Email:	Email: Lucas@rchi.ca
Phone No.:	Phone No.: 613-304-9970
Lucas Russell Inspector's name:	10008 WETT No.:
Reason(s) for inspection: real estate sale	
Level of inspection requested: O Lev	el 1 O Level 2 O Level 3
Date of request: 05/17/2025	Date of inspection: 05/24/2025

Note: inspection results shown are what was present/noted at time of inspection.

This report documents findings at the time of the inspection. Compliance is referenced to currently published applicable codes and standards.

Wood Energy Technology Transfer Inc. Wood Stove and Flue Pipe
Certification Standard: 🖌 ULC S627 🗌 EPA 🗌 CSA B415 🗌 Uncertified 🗌 Unknown
Listing Agency: OULC OCSA WH/ETL OTL Other: Make: Regency Model: Medium Freestanding Serial #: 313086
Installation manual available: • Yes ONo Flue Collar Size: 6 inch
Alcove approved: ON/A OYes ONo OUTI
Mobile home approved: ON/A OYes ONo OUTI
Installed by: Date: 1992 Unknown:
Installed in: Residence OMobile Home OCombustible Alcove
OGarage OOther:
Appliance location: OBasement OMain Floor Other (specify):
Connected to: O Masonry chimney O Masonry chimney with stainless steel liner
Factory-built chimney Other (specify):
Does the unit share a venting system with another appliance: OYes ONo

Inspection Results: Indicate inspection results for each component. Code compliance includes proper use of listed components. N/A = Not Applicable UTI = Unable To Inspect.

All non-compliance ratings should be considered for comment.

An inspection at any level can be expected to include some components marked UTI.

CLEARANCES	REQUIRED	Actual(s)	CODE COMPLIANCE
1. Combustible side wall			• N/A OYes ONo OUTI
2. Combustible rear wall			• N/A OYes ONo OUTI
3. Combustible corner	9.5"	9.5"	ON/A OYes ONo OUTI
4. Top / ceiling	-		ON/A OYes ONo OUTI
5. Shielding rear			• N/A OYes ONo OUTI
6. Shielding right side			• N/A OYes ONo OUTI

7. Shielding left side	\odot N/A \bigcirc Yes \bigcirc No \bigcirc UTI
8. Shielding corner	N/A O Yes O No O UTI
9. Ember pad / material	\bigcirc N/A \bigcirc Yes \bigcirc No \bigcirc UTI
10. Ember pad / front	N/A O Yes O No O UTI
11. Ember pad / rear	N/A O Yes O No O UTI
12. Ember pad / right side	N/A O Yes O No O UTI
13. Ember pad / left side	N/A O Yes O No O UTI
14. Ember pad / corner	O N/A O Yes O No O UTI
15. Radiant heat protection / material	N/A O Yes O No O UTI
16.	
17.	
Flue Pipe Type: OSingle-wall ODoub	le-wall OULC S641 Diameter: 6 inch
18. Clearances	O N/A O Yes O No O UTI
19. Total length	O N/A O Yes O No O UTI
20. Elbows	N/A O Yes O No O UTI
21. Fastening	O N/A O Yes O No O UTI
22. Allowance for expansion	O N/A • Yes O No O UTI
23. Flue pipe orientation	O N/A O Yes O No O UTI
24. Flue pipe slope	O N/A O Yes O No O UTI
25. Material	O N/A • Yes O No O UTI
26. Pipe shielding	• N/A O Yes O No O UTI
7. Support	• N/A O Yes O No O UTI
8.	
9.	
0.	
	N/A O Yes O No O UTI
Connection to masonry chimney Connection to factory-built	

Wood Stove and Flue Pipe - pa	ge 3		
• OTHER CONSIDERATIONS	Comments		
33. Outdoor air connection		present	
34. Carbon monoxide alarm		present	
35. Smoke alarm		present	*

Additional information:

Date: 05/24/2025

File Reference #: _____

Photos taken: • Yes () No
This checklist contains 2	pages in total. This report contains 4 pages in total.
Comments and Observati All non-compliance ratings	ons: should be considered for comment.
WOOD STOVE AND FLUE PI	PE
21. Each flue pipe connection t has 2 screws installed at flue p for expansion. Corrective Action Required	requires a minimum of 3 screws per connection. Actual installation ipe connection. *****Telescopic section must have no screws installed
*****The flue pipe has a thick l Cleaning Required	ayer of creosote build up inside. Cleaning is needed
Please	attach additional page(s) for this section.
Please	attach additional page(s) for this section.
Please Customer Signature:	
	Inspector Signature:

Wood Energy Technology Transfer Inc.	ETT RECOMMENDED INSPECTION CHECKLIST Factory-built Chimney
Chimney Type: OULC	604 (Factory-built Type A) OULC S610 (Factory-built Fireplace Chimney)
OULO	S629 (650°C) OUncertified OUnknown
Listing Agency:	C OCSA OWH/ETL OOTL OOther:
Make: Selkirk	Model: SC-1
Installation manual availabl	e: • Yes ONo
Installed by:	
Installed in: OResidence	O Mobile Home O Garage
O Other:	
Total height: <u>30 ft</u>	Flue Size: <u>6 inch</u> Inside Installation Outside Installation
	Make:Model:FreestandingSerial #:313086
Connected to:	_ Make: Model: Serial #:

Inspection Results: Indicate inspection results for each component. Code compliance includes proper use of listed components. N/A = Not Applicable UTI = Unable To Inspect.

All non-compliance ratings should be considered for comment.

An inspection at any level can be expected to include some components marked UTI.

COMPONENT		CODE C	OMPLIANCE	
1. Horizontal extension beyond inside wall surface	• N/A	O Yes	O No	O UTI
2. Wall radiation shield	• N/A	OYes	ONo	O UTI
3. Clean-out tee and cap	• N/A	O Yes	O No	O UTI
4. Wall supports	• N/A	O Yes	O No	O UTI
5. Ceiling support	O N/A	• Yes	O _{No}	O UTI
6. Support spacing	• N/A	O Yes	ONo	O UTI
7. Chimney offsets	O N/A	• Yes	O No	O UTI
8. Offset support	O N/A	• Yes	ONo	O UTI
9. Firestopping	• N/A	O Yes	O _{No}	O UTI

Factory-built Chimney - page 2

....

Component		Code C	OMPLIANCE	anna an Anna Anna Anna Anna Anna Anna A
10. Attic radiation shield	O N/A	• Yes	ONo	Outi
11. Other radiation shield(s)	• N/A	O Yes	O No	Outi
12. Enclosed through living space	• N/A	OYes	O _{No}	Outi
13. Roof flashing/storm collar	O N/A	• Yes	O _{No}	OUTI
14. Roof braces	• N/A	OYes	O _{No}	Outi
15. Rain cap	O N/A	• Yes	O No	Outi
16.	O N/A	OYes	O _{No}	Outi
17. Height above roof surface	O N/A	• Yes	O _{No}	Outi
18. Chimney clearance to combustibles	O N/A	• Yes	ON0	Outi
19.	O N/A	OYes	O _{No}	Outi
20.	O N/A	O Yes	O No	Outi
Other Considerations				
21. Areas of chimney enclosed or hidden	• N/A	O Yes	O No	Outi
22.				
23.				

Additional information:

Date: 05/24/2025

File Reference #: _____

File reference No.:	
Photos taken: • Yes) No
This checklist contains 2	pages in total. This report contains _4 pages in total.
Comments and Observation	ns:
	ould be considered for comment.
FACTORY BUILT CHIMNEY	
****Thick layer of creosote build Cleaning Required	up is suspected inside chimney.
Please a	ttach additional page(s) for this section.
Please a	ttach additional page(s) for this section.
Please a	
Please a	