

REFITTING LIST

Renewal and check of all security installations (life raft expired in date 04/2016)
Left engine MMDS control unit recovery
A/C compressor presence of oxidation and rust
Outboard tender engine ordinary maintenance
Anchor and chain oxidized
Rust and matt on steel and small parts
Dishwasher handle damaged
Abrasions on rubberized canvas of tender's tubulars
Teak deterioration in external areas Main deck and Fly bridge
Internal carpets stained
Ceilings coating in living room detached and degraded
Internal area wooden floors signed and damaged
Stern mirror detached parts
Superstructure gelcoat splits and cracks
Navigating bridge armchair upholstery damaged
Cockpit table slightly damaged with stains and scratches
Sittings pillows damaged and stained
Domotic system broken and shows the following information on the display "apertura della
connessione al plc non riuscita"
Generator battery charger broken
Bathing stairs, gangway, table and lights control panel not working