

Manual Welding Machine

- 20K 2000W
- Home use
- Humidity: $\leq 85\%$ RH;
- Ambient temperature: 0 °C - 40 °C;
- Use space: the distance between surrounding objects and equipment shall not be less than 150 mm, and the distance between surrounding objects and heat sink shall not be less than 200 mm.
- The transducer chip and tool head must adopt active heat dissipation, and must be blown up or other heat dissipation methods.


The complete machine:



Process:












ROTATE UP











Assemble the transducer









D_20200528_162304

