

# **Product Data Sheet**

**OK Autrod 5183** 

G 'Gas-shielded metal-arc welding'

Signed by	Approved by	Reg no	Cancelling	Reg date	Page
Mats Linde	Per-Åke Pettersson/Christos Skodras	EN005027	EN004338	2009-11-23	1 (2)

### **REASON FOR ISSUE**

LR added.

#### **GENERAL**

OK Autrod 5183 was developed to provide the highest strengths possible in the as welded condition of alloy AA 5083 and other similar high magnesium alloys. The more common OK Autrod 5356 will typically fail to meet the as-welded tensile requirements of AA 5083. The alloy is typically utilised in marine and structural applications where high strengths, high fracture toughness for impact resistance and exposure to corrosive elements are important. The alloy is not recommended for elevated temperature applications due to its susceptibility to stress corrosion cracking. The alloy is non-heat treatable.

Shielding Gas: I1, I3 (EN ISO 14175) Alloy Type: AlMgMn **CLASSIFICATIONS Wire Electrode APPROVALS SFA/AWS A5.10** ABS ER5183 ER5183 for dim. 1.2 and 1.6 mm EN ISO 18273 S AI 5183 (AIMg4,5Mn0,7(A)) BV WC CE EN 13479 ClassNK KAI5RCG(I-1)(I-4) (only for lots beginning with **CWB** AWS A5.10 (Item no ending with A) DB 61.039.03 DNV 5183 (WC) GL RAIMg4.5 LR WC/I-1 VdTÜV 04666

### **CHEMICAL COMPOSITION**

# Wire/Strip (%)

	Min	Max
Si		0.40
Mn	0.50	1.00
Cr	0.05	0.25
Cu		0.10
Ti		0.15
Zn		0.25
Fe		0.40
Be		0.0003
Mg	4.3	5.2
Other each		0.05
Others tot		0.15



# **Product Data Sheet**

**OK Autrod 5183** 

G 'Gas-shielded metal-arc welding'

Signed by	Approved by	Reg no	Cancelling	Reg date	Page
Mats Linde	Per-Åke Pettersson/Christos Skodras	EN005027	EN004338	2009-11-23	2 (2)

## **MECHANICAL PROPERTIES OF WELD METAL**

### **All Weld Metal**

	As welded		
Properties	Min	Тур	
Rp0.2 (MPa) Rm (MPa) A4-A5 (%)	125 275 17	140 290 25	
Charpy V at 20°C (J/cm2)	20	30	

## **ECONOMICS & CURRENT DATA**

Dimension (mm)	Curre	nt (A)	W	η	ı	4	Fe	ed		U
Ø	Min	Max	Nom	Nom	Min	Max	Min	Max	Min	Max
1.0	90	210	16						15	26
1.2	140	260	19						20	29
1.6	190	350	25						25	30
2.4	280	400	30						26	31

**W** = Gas consumption (I / min)

η = Recovery, g weld metal / 100g wire (%)H = Deposit rate (kg weld metal / hour arc time)

Feed = Feeding rate (m/min)
U = Arc voltage (V)

## **OTHER DATA**

Clean material is essential for a good weld quality. Remove oxide, dirt, oil, humidity etc. before welding. If brushing use a stainless steel wire brush. Preheating to 65 °C can be used to reduce risk of porosity.