

INDICATOR CENTERING HOLDER



Code

6294-1A

- Center cylinders or holes on machine tools
- Can be used with dial test indicators or dial indicators



6294-1A

