









Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, GN, ...

Pos.	Part No.
1	A 861 521 XX
2	A 861 417 XX
3	A 861 397 NU
5	B 961 383 XX
6	A 861 227 XX
7	A 964 520 NU
9	A 961 172 NU
10	B 960 900 XX
11	A 961 230 XX



P	50°C	15°C	27	33	41	48	50
0,3 MPa 3 bar	65°C	15°C	33	42	53	63	65
	85°C	15°C	41	53	68	83	85




Ideal Standard

CONNECT AIR


A 7046 .. A 7047 .. A 7048 .. A 7049 ..

0923 / A 868 880 R1
Made in Germany


A 7049 ..




A 7048 ..



A 7046











A 7047



Ideal Standard International NV
Corporate Village - Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium

www.idealstandardinternational.com





	P	bar		MAX. 10		5		Q (3 bar)
	T	°C		MAX. 85		65		I/min
						40		5