

TB-89994 / January 25, 2017

---

## NEW MOTOR FOR RPU80/160

<b>Product:</b>	000-13765-001 000-13766-001 21116165 21118203
<b>Product Description:</b>	RPU80/160
<b>Software Version:</b>	NA
<b>Effective Date:</b>	01.01.2017
<b>Inspect/Update Current Inventory:</b>	No

---

## REPLACING LEMAC WITH PARVALUX MOTOR

### New motor


After many years of service, LEMAC motors used in the RPU80 and RPU160, have come to End of Life and will be replaced by motors from PARVALUX. The performance and quality will be the same, so the part numbers on the pump units will remain unchanged.

The new motor is marked with a tag including the name and specification from the manufacturer, as shown below.

**OLD LEMAC**



**NEW PARVALUX (shown with pump unit)**



## Spare motors

Spare part motors for replacing old LEMAC and FRACMO motors on existing pumps are listed below.

- 000-13953-001 RPU80 MOTOR, PARVALUX
- 000-13954-001 RPU160 MOTOR, PARVALUX


## Spare brushes

The brushes used in new motors are the same for both the RPU80 and RPU160.

- 000-13960-001 RPU80/160 BRUSH PARVALUX, PAIR



The images below illustrate how easy it is to access and replace the brush.





## RPU300

The motor for the RPU300 will also be changed in near future. A separate bulletin will be issued.

### For More Information:

U.S. Based Resellers Technical and Order Support: (800) 324-4737

Canada Based Resellers Technical Support: (855) 361-1564

You may also send any inquiries via email to the addresses listed below, according to your sales-group classification:

- OEM/Boatbuilder – [oem-bb@navico.com](mailto:oem-bb@navico.com)
- International/Latin America – [international@navico.com](mailto:international@navico.com)
- National Retail – [retail@navico.com](mailto:retail@navico.com)
- Dealers/Distributors – [orders@navico.com](mailto:orders@navico.com)