

## **Premier House, Edgware | Fire safety situation report**

### **Update 31 July 2020**

The managing agents have received confirmation of support from the Government in the region of £160,000. Exploratory works are required before full works to replace the cladding may commence, however the exploratory works have been delayed due to lockdown measures and a revised start date is awaited. It has been confirmed that the cladding will be replaced by a compliant aluminium rainscreen system with an identical finish to the existing paneling in place.