## **BUILDING REGULATION COMPLIANCE Calculation Type: New Build (As Designed)**



Property Reference	19037 Plot 049					Issue	d on Date	21/04/2019
Assessment	49				Prop Type Ref	Helmsl	ey semi	
Reference								
Property	49, The Paddocks,	Green Man	Road, N	avenby, Lincoln,	LN5			
SAP Rating			83 B	DER	18.38	TE	R	18.40
Environmental			85 B	% DER <ter< td=""><td></td><td></td><td>0.08</td><td></td></ter<>			0.08	
CO₂ Emissions (t/year	)		1.50	DFEE	50.83	TF	EE	56.91
General Requirement	s Compliance		Pass	% DFEE <tfee< td=""><td></td><td></td><td>10.67</td><td></td></tfee<>			10.67	
Assessor Details	1r. Robert Atherton,	Low Carbor	Box Lim	ited, Tel: 075409	977134,	As	sessor ID	F291-0001
	bert@lowcarbonbo	x.co.uk						
Client								
SUMARY FOR INPUT D	ATA FOR New Build	(As Designe	ed)					
Criterion 1 – Achieving	the TER and TFEE ra	ite						
a TER and DER								
Fuel for main heati	ng		Mains g	as				
Fuel factor			1.00 (m	ains gas)				
Target Carbon Diox	ide Emission Rate (Ti	ER)	18.40				kgCO <sub>2</sub> /m <sup>2</sup>	
Dwelling Carbon Di	oxide Emission Rate	(DER)	18.38				$kgCO_2/m^2$	Pass
			-0.02 (-0	0.1%)			$kgCO_2/m^2$	
b TFEE and DFEE								
Target Fabric Energ	y Efficiency (TFEE)		56.91				kWh/m²/yr	
Dwelling Fabric Ene	rgy Efficiency (DFEE)		50.83				kWh/m²/yr	
			-6.1 (-10	0.7%)			kWh/m²/yr	Pass
Criterion 2 – Limits on	design flexibility							
<b>Limiting Fabric Star</b>	ndards							
2 Fabric U-values								
Element		Average			Highest			
External wal	I	0.19 (max	x. 0.30)		0.19 (max. 0.7	0)		Pass
Party wall		0.00 (max	x. 0.20)		-			Pass
Floor		0.16 (max	,		0.16 (max. 0.7	•		Pass
Roof		0.11 (max			0.11 (max. 0.3			Pass
Openings		1.38 (max	x. 2.00)		1.40 (max. 3.3	0)		Pass
2a Thermal bridgin	g							
Thermal bridgin	g calculated from lin	ear therma	l transmit	ttances for each	junction			
3 Air permeability								
Air permeability	at 50 pascals		5.75 (de	esign value)		m³/(h	ı.m²) @ 50 Pa	I
Maximum			10.0			m³/(h	ı.m²) @ 50 Pa	Pass

4 Heating efficiency

Limiting System Efficiencies

This report has been produced by an accredited Elmhurst member whose work is subject to quality assurance audits. The data used to produce the report has been verified by the Elmhurst members' portal.





#### **BUILDING REGULATION COMPLIANCE Calculation Type: New Build (As Designed)**



Main heating system	Boiler system with radiators or underfloor - Mains gas Data from database	Pass
	Vaillant ecoFIT sustain 615 VU 156/6-3 (H-GB)	
	Efficiency: 89.8% SEDBUK2009 Minimum: 88.0%	
Secondary heating system	None	
5 Cylinder insulation		
Hot water storage	Measured cylinder loss: 1.31 kWh/day Permitted by DBSCG 2.10	Pass
Primary pipework insulated	Yes	Pass
6 Controls		
Space heating controls	Time and temperature zone control	Pass
Hot water controls	Cylinderstat	Pass
	Independent timer for DHW	Pass
Boiler interlock	Yes	Pass
7 Low energy lights		
Percentage of fixed lights with low-energy fittings	100 %	
Minimum	75 %	Pass
8 Mechanical ventilation		
Continuous extract system (decentralised)		
Specific fan power	0.0900 0.0900 0.1100	
Maximum	0.7	Pass
Criterion 3 – Limiting the effects of heat gains in su	mmer	
9 Summertime temperature		
Overheating risk (East Pennines)	Not significant	Pass
Based on:		
Overshading	Average	
Windows facing North	7.60 m <sup>2</sup> , No overhang	
Windows facing East	2.71 m², No overhang	
Windows facing West  Air change rate	5.24 m², No overhang 4.00 ach	
Blinds/curtains		<del></del>
Criterion 4 – Building performance consistent with	None PEEC rate	
	DER AND DEEL FALE	
Party Walls		
Туре	U-value	
Filled Cavity with Edge Sealing	0.00 W/m²K	Pass
Air permeability and pressure testing		
3 Air permeability	2// 2/	
Air permeability at 50 pascals	5.75 (design value) m <sup>3</sup> /(h.m <sup>2</sup> ) @ 50 Pa	
Maximum	10.0 m <sup>3</sup> /(h.m <sup>2</sup> ) @ 50 Pa	a Pass

This report has been produced by an accredited Elmhurst member whose work is subject to quality assurance audits. The data used to produce the report has been verified by the Elmhurst members' portal.





## **BUILDING REGULATION COMPLIANCE Calculation Type: New Build (As Designed)**



#### 10 Key features

Party wall U-value Roof U-value Door U-value

0.00	W/m²K
0.11	W/m²K
0.91	W/m²K

This report has been produced by an accredited Elmhurst member whose work is subject to quality assurance audits. The data used to produce the report has been verified by the Elmhurst members' portal.







<b>Property Reference</b>	19037 Plot	049				Iss	ued on Da	te 21/0	04/2019
Assessment	49				Prop Type	Ref Hel	msley semi		
Reference									
Property	49, The Pac	ldocks, Greer	n Man Road, N	avenby, Lincoln,	LN5				
SAP Rating			83 B	DER	18	.38	TER		18.40
Environmental			85 B	% DER <ter< td=""><td></td><td></td><td>0.08</td><td></td><td></td></ter<>			0.08		
CO₂ Emissions (t/yea	ar)		1.50	DFEE	50	.83	TFEE		56.91
<b>General Requiremer</b>	nts Compliance		Pass	% DFEE <tfee< td=""><td></td><td></td><td>10.67</td><td></td><td></td></tfee<>			10.67		
	Mr. Robert Ath robert@lowcar			ited, Tel: 075409	77134,		Assessor I	D F29	1-0001
Client									
SUMMARY FOR INPU	T DATA FOR: N	lew Build (As	Designed)						
Orientation		North							
Property Tenure		Unknown							
Transaction Type		New dwellin	ng						
Terrain Type		Suburban							
1.0 Property Type		House, Sem	i-Detached						
2.0 Number of Storeys		2							
3.0 Date Built		2019							
4.0 Sheltered Sides		3							
5.0 Sunlight/Shade		Average or u	unknown						
6.0 Measurements		G	round Floor: 1st Storey:	Heat Loss Perimet 22.85 m 22.85 m	er Inte	ernal Floo 44.93 m 44.93 m	2	verage Stor 2.39	-
7.0 Living Area								2.68 ו	m
8.0 Thermal Mass Parai		16.05			m²			2.68	m
	neter	Precise calcu	ulation		m²			2.68	m
Thermal Mass	meter		ulation		m² kJ/m²K			2.68	m
	meter	Precise calcu	ulation					2.68 (	n
9.0 External Walls Description	Type	Precise calcu 203.95	ulation			U-Value (W/m²K)	Карра	2.68 (Gross Area (m²)	Nett Area (m²)
9.0 External Walls		Precise calcu 203.95	struction			U-Value	Карра	Gross Area	Nett Area
9.0 External Walls Description  External Wall  9.1 Party Walls	<b>Type</b> Cavity Wa	Precise calcu 203.95	<b>struction</b> er			U-Value (W/m²K)	Kappa (kJ/m²K) 72.24	Gross Area (m²) 115.85	Nett Area (m²) 98.17
9.0 External Walls Description  External Wall	Туре	Precise calcu 203.95	struction			U-Value (W/m²K)	Kappa (kJ/m²K)	Gross Area (m²)	Nett Area (m²)
9.0 External Walls Description  External Wall  9.1 Party Walls	<b>Type</b> Cavity Wa	Precise calculated 203.95  Con Con Con Sty with Sing	struction er struction	n dabs both sides, lig	kJ/m²K	U-Value (W/m²K) 0.19	Kappa (kJ/m²K) 72.24 U-Value	Gross Area (m²) 115.85	Nett Area (m²) 98.17
9.0 External Walls Description  External Wall  9.1 Party Walls Description	Type  Cavity Wa  Type  Filled Cav  Edge Seal	Precise calculated 203.95  Con Con Con Sty with Sing	struction er struction	_	kJ/m²K	U-Value (W/m²K) 0.19	Kappa (kJ/m²K) 72.24 U-Value (W/m²K)	Gross Area (m²) 115.85 Kappa (kJ/m²K)	Nett Area (m²) 98.17 Area (m²)
9.0 External Walls Description  External Wall  9.1 Party Walls Description  Party Wall 1  9.2 Internal Walls	Type  Cavity Wa  Type  Filled Cav Edge Seal	Precise calculated 203.95  Con Other Con Struction  Sterboard on time	struction er struction gle plasterboard or cks, cavity or cavity	_	kJ/m²K	U-Value (W/m²K) 0.19	Kappa (kJ/m²K) 72.24 U-Value (W/m²K)	Gross Area (m²) 115.85 Kappa (kJ/m²K) 110.00	Nett Area (m²) 98.17  Area (m²) 34.02
9.0 External Walls Description  External Wall  9.1 Party Walls Description  Party Wall 1  9.2 Internal Walls Description  Internal Partition 2	Type  Cavity Wa  Type  Filled Cav Edge Seal  Con	Precise calculated 203.95  Condition Other Conditions block in the condition of the conditi	struction er struction gle plasterboard or cks, cavity or cavity	_	kJ/m²K	U-Value (W/m²K) 0.19	Kappa (kJ/m²K) 72.24  U-Value (W/m²K) 0.00	Gross Area (m²) 115.85 Kappa (kJ/m²K) 110.00	Nett Area (m²) 98.17  Area (m²) 34.02  Area (m²) 102.68



Regs Region: England Elmhurst Energy Systems SAP2012 Calculator (Design System) version 4.10r08



Pescription   Type   Construction	10.2 Internal Ceilings										
11.0   Plasterboard ceiling, carpeted chipboard floor   Plast Loss Floors   Type   Construction   Type   Construction   Cround Floor - Solid   Suspended concrete floor, carpeted   Cround Floor - Solid   Cround Floor - Solid   Suspended concrete floor, carpeted   Cround Floor - Solid   Cround Floor - Solid Floor - Solid   Cround Floor - Solid Floor -	Description	(	Construction								
1.0   Heal Loss Floors											. ,
Pescription   Type   Construction	Internal Ceiling 1		Plasterboard ceiling, carpeted chipboard floor							9.00	44.93
Control   Floor   Construction   C	11.0 Heat Loss Floors		_								
11.2 Internal Floors   Description   Construction	Description	Туре	Cons	struction							
Pescription	Ground Floor	Groun	d Floor - Solid Susp	ended concrete	floor, carp	eted					. ,
Plasterboard celling, carpeted chipboard floor	11.2 Internal Floors										
12.0 Opening Types   Data Source   Type   Glazing   Glazing   Glazing   Glazing   Argon   Filled   Frame   Frame   Frame   Factor   Window   Front Door   Manufacture   Solid Door   Manufacture   Window   Double Low-E Soft 0.1   0.71   0.70   1.40   0.71   0.70   1.40   0.71   0.70   1.50   0.71   0.70   1.50   0.71   0.70   1.50   0.71   0.70   0.7	Description	(	Construction								
Description   Data Source   Type   Glazing   Glazing   Argon   Gay   Frame   Type	Internal Floor 1	1	Plasterboard ceiling,	carpeted chipbo	oard floor						
Description   Data Source   Type   Glazing   Glazing   Argon   Gay   Frame   Type	12.0 Opening Types										
Front Door   Manufacture   Mindow   Double Low-E Soft 0.1   0.71   0.70   1.40		Data Source	Туре	Glazing		-	_	G-valu			U Value (W/m²K)
Windows   Manufacture   Window   Double Low-E Soft 0.1   0.71   0.70   1.40	Front Door		Solid Door						,,		, , ,
HG Door Manufacture Half Glazed Door Double Low-E Soft 0.1 0.71 0.70 1.50 Garage door Manufacture Door to Corridor r Patio Doors Manufacture Window Double Low-E Soft 0.05 0.63 0.70 1.40 0.91 0.91 0.63 0.63 0.70 1.40 0.91 0.63 0.63 0.70 1.40 0.91 0.63 0.63 0.70 1.40 0.91 0.63 0.63 0.70 1.40 0.91 0.63 0.63 0.70 0.63 0.70 1.40 0.70 0.63 0.63 0.70 0.70 0.70 0.70 0.70 0.70 0.70 0.7	Windows		Window	Double Low-E	Soft 0.1			0.71		0.70	1.40
Garage door Fation Door to Corridor Fation Door to Corridor Fation Doors    Manufacture Door to Corridor Fation Door    Manufacture Window Double Low-E Soft 0.05    13.0 Openings Name	HG Door	r Manufacture	Half Clared Desi-	Double Law 5	Soft 0.1			0.71		0.70	1.40
Patio Doors	HG D001		Hall Glazed Dool	Double Low-E	3011 0.1			0.71		0.70	1.50
Patio Doors   Manufacture   Window   Double Low-E Soft 0.05   0.63   0.70   1.40    13.0 Openings   Name   Opening Type   Location   Orientation   Type   Ratio   Overhang   Wide   Width   Height   Count   Area   Curtain   Closed   Type	Garage door		Door to Corridor								0.91
Name Opening Type Location Orientation Curtain Type Ratio Overhang (m) (m) (m) (m) (m) (n) (n) (n) (n) (n) (n) (n) (n) (n) (n	Patio Doors	Manufacture	Window	Double Low-E	Soft 0.05			0.63		0.70	1.40
Name Opening Type Location Orientation Curtain Type Ratio Overhang (m) (m) (m) (m) (m) (n) (n) (n) (n) (n) (n) (n) (n) (n) (n	13.0 Openings										
Front Door   Solid Door   [1] External Wall   North   None   0.00   7.60		ening Type	Location	Orientation		_			_		Curtain
Front Windows   Window   Mindow   Min	Front Door Soli	d Door	[1] External Wall	North	Туре	капо	Overnang	(m)	(m)		Closed
None   Side win   Window   Side win   Window   Side win   Window   Side win   Side win   Window   Side win					None	0.00					
1.0   1.0	Rear Windows Wir										
15.0 Draught Proofing 16.0 Draught Lobby    Total Bridging   Calculate Bridges	Side win Wir	ndow	[1] External Wall	East	None	0.00				2.71	
15.0 Draught Proofing 16.0 Draught Lobby    Total Bridging   Calculate Bridges	14.0 Conservatory		None								
17.0 Thermal Bridging 17.1 List of Bridges Source Type Independently assessed Independently	•						%				
T7.0 Thermal Bridging  17.1 List of Bridges  Source Type  Bridge Type  Independently assessed  Independently assessed  E1 Steel lintel with perforated steel base plate  Independently assessed  E3 Sill  Independently assessed  E4 Jamb  Independently assessed  E5 Ground floor (normal)  Independently assessed  E6 Intermediate floor within a dwelling  Independently assessed  E10 Eaves (insulation at ceiling level)  Independently assessed  E12 Gable (insulation at ceiling level)  Independently assessed  E16 Corner (normal)  Independently assessed  E17 Corner (inverted – internal area greater than external area)  Table K1 - Default  E25 Staggered party wall between dwellings  Table K1 - Default  P2 Party wall - Intermediate floor within a ceiling level)  Table K1 - Default  P2 Party wall - Intermediate floor within a ceiling level)  Fable K1 - Default  P4 Party wall - Roof (insulation at ceiling level)  Fable K1 - Default  P4 Party wall - Roof (insulation at ceiling level)  Fable K1 - Default  P4 Party wall - Roof (insulation at ceiling level)  Fable K1 - Default  P4 Party wall - Roof (insulation at ceiling level)  Fable K1 - Default  P4 Party wall - Roof (insulation at ceiling level)  Fable K1 - Default  P4 Party wall - Roof (insulation at ceiling level)  Fable K1 - Default  Fable K1 - Defa	0 0						, ,				
Source Type Bridge Type Length Psi Imported Reference: Independently assessed E1 Steel lintel with perforated steel base plate 12.92 0.358 No CBA-312 Independently assessed E3 Sill 10.33 0.020 No CBA-314 Independently assessed E4 Jamb 31.65 0.016 No CBA-315 Independently assessed E5 Ground floor (normal) 22.85 0.094 No CBA-301 Independently assessed E6 Intermediate floor within a dwelling 22.85 0.000 No CBA-301 Independently assessed E10 Eaves (insulation at ceiling level) 10.58 0.036 No Plasmor Independently assessed E12 Gable (insulation at ceiling level) 12.27 0.077 No CBA-310 Independently assessed E16 Corner (normal) 30.42 0.051 No CBA-316 Table K1 - Approved E17 Corner (inverted – internal area greater than 10.14 -0.090 No ACD  Table K1 - Default E25 Staggered party wall between dwellings 10.14 0.120 No Table K1 - Default P1 Party wall - Ground floor 6.71 0.160 No Table K1 - Default P2 Party wall - Intermediate floor within a dwelling level) 6.71 0.240 No Y-value				idaas							
Source Type Independently assessed Independen			Calculate Bi	luges							
Independently assessed E1 Steel lintel with perforated steel base plate 12.92 0.358 No CBA-312 Independently assessed E3 Sill 10.33 0.020 No CBA-314 Independently assessed E4 Jamb 31.65 0.016 No CBA-315 Independently assessed E5 Ground floor (normal) 22.85 0.094 No CBA-315 Independently assessed E6 Intermediate floor within a dwelling 22.85 0.000 No CBA-301 Independently assessed E10 Eaves (insulation at ceiling level) 10.58 0.036 No Plasmor Independently assessed E12 Gable (insulation at ceiling level) 12.27 0.077 No CBA-310 Independently assessed E16 Corner (normal) 30.42 0.051 No CBA-316 Table K1 - Approved E17 Corner (inverted – internal area greater than 10.14 -0.090 No ACD external area)  Table K1 - Default E25 Staggered party wall between dwellings 10.14 0.120 No Table K1 - Default P1 Party wall - Ground floor 6.71 0.160 No Table K1 - Default P2 Party wall - Intermediate floor within a 6.71 0.000 No Modwelling Table K1 - Default P4 Party wall - Roof (insulation at ceiling level) 6.71 0.240 No Y-value 0.065		Bridge	Type			Length	Psi	Imported	Reference:		
Independently assessed E3 Sill 10.33 0.020 No CBA-314 Independently assessed E4 Jamb 31.65 0.016 No CBA-315 Independently assessed E5 Ground floor (normal) 22.85 0.094 No CBA-301 Independently assessed E6 Intermediate floor within a dwelling 22.85 0.000 No CBA-303 Independently assessed E10 Eaves (insulation at ceiling level) 10.58 0.036 No Plasmor Independently assessed E12 Gable (insulation at ceiling level) 12.27 0.077 No CBA-310 Independently assessed E16 Corner (normal) 30.42 0.051 No CBA-316 Table K1 - Approved E17 Corner (inverted – internal area greater than 10.14 -0.090 No ACD external area) Table K1 - Default E25 Staggered party wall between dwellings 10.14 0.120 No Table K1 - Default P1 Party wall - Ground floor 6.71 0.160 No Table K1 - Default P2 Party wall - Intermediate floor within a 6.71 0.000 No dwelling Table K1 - Default P4 Party wall - Roof (insulation at ceiling level) 6.71 0.240 No  Y-value 0.065 W/m²K	***	_		ed steel base pla		_					
Independently assessed E5 Ground floor (normal) 22.85 0.094 No CBA-301 Independently assessed E6 Intermediate floor within a dwelling 22.85 0.000 No CBA-303 Independently assessed E10 Eaves (insulation at ceiling level) 10.58 0.036 No Plasmor Independently assessed E12 Gable (insulation at ceiling level) 12.27 0.077 No CBA-310 Independently assessed E16 Corner (normal) 30.42 0.051 No CBA-316 Table K1 - Approved E17 Corner (inverted – internal area greater than external area) Table K1 - Default E25 Staggered party wall between dwellings 10.14 0.120 No Table K1 - Default P1 Party wall - Ground floor 6.71 0.160 No Table K1 - Default P2 Party wall - Intermediate floor within a dwelling M4 P4 Party wall - Roof (insulation at ceiling level) 6.71 0.240 No Y-value 0.065 W/m²K						10.33	0.020	No	CBA-314		
Independently assessed E6 Intermediate floor within a dwelling 22.85 0.000 No CBA-303 Independently assessed E10 Eaves (insulation at ceiling level) 10.58 0.036 No Plasmor Independently assessed E12 Gable (insulation at ceiling level) 12.27 0.077 No CBA-310 Independently assessed E16 Corner (normal) 30.42 0.051 No CBA-316 Table K1 - Approved E17 Corner (inverted – internal area greater than external area) 10.14 -0.090 No ACD External area) Table K1 - Default E25 Staggered party wall between dwellings 10.14 0.120 No Table K1 - Default P1 Party wall - Ground floor 6.71 0.160 No Table K1 - Default P2 Party wall - Intermediate floor within a dwelling Table K1 - Default P4 Party wall - Roof (insulation at ceiling level) 6.71 0.240 No Y-value 0.065 W/m²K	Independently assess	sed E4 Jaml	b			31.65	0.016	No	CBA-315		
Independently assessed E10 Eaves (insulation at ceiling level) 10.58 0.036 No Plasmor Independently assessed E12 Gable (insulation at ceiling level) 12.27 0.077 No CBA-310 Independently assessed E16 Corner (normal) 30.42 0.051 No CBA-316 Table K1 - Approved E17 Corner (inverted – internal area greater than external area) 10.14 -0.090 No ACD E17 Corner (inverted – internal area greater than external area) 10.14 0.120 No Table K1 - Default E25 Staggered party wall between dwellings 10.14 0.120 No Table K1 - Default P1 Party wall - Ground floor 6.71 0.160 No Table K1 - Default P2 Party wall - Intermediate floor within a 6.71 0.000 No dwelling Table K1 - Default P4 Party wall - Roof (insulation at ceiling level) 6.71 0.240 No Y-value 0.065 W/m²K	Independently assess	sed E5 Grou	und floor (normal)			22.85	0.094	No	CBA-301		
Independently assessed E12 Gable (insulation at ceiling level) 12.27 0.077 No CBA-310 Independently assessed E16 Corner (normal) 30.42 0.051 No CBA-316 Table K1 - Approved E17 Corner (inverted – internal area greater than 10.14 -0.090 No ACD  Table K1 - Default E25 Staggered party wall between dwellings 10.14 0.120 No Table K1 - Default P1 Party wall - Ground floor 6.71 0.160 No Table K1 - Default P2 Party wall - Intermediate floor within a 6.71 0.000 No dwelling Table K1 - Default P4 Party wall - Roof (insulation at ceiling level) 6.71 0.240 No  Y-value 0.065 W/m²K	Independently assess	sed E6 Inte	rmediate floor withi	n a dwelling		22.85	0.000	No	CBA-303		
Independently assessed E16 Corner (normal) 30.42 0.051 No CBA-316  Table K1 - Approved E17 Corner (inverted – internal area greater than external area) 10.14 -0.090 No ACD  Table K1 - Default E25 Staggered party wall between dwellings 10.14 0.120 No  Table K1 - Default P1 Party wall - Ground floor 6.71 0.160 No  Table K1 - Default P2 Party wall - Intermediate floor within a 6.71 0.000 No dwelling  Table K1 - Default P4 Party wall - Roof (insulation at ceiling level) 6.71 0.240 No  Y-value 0.065 W/m²K	Independently assess	sed E10 Eav	ves (insulation at cei	ling level)		10.58	0.036	No	Plasmor		
Table K1 - Approved  E17 Corner (inverted – internal area greater than external area)  Table K1 - Default  E25 Staggered party wall between dwellings  Table K1 - Default  P1 Party wall - Ground floor  Table K1 - Default  P2 Party wall - Intermediate floor within a dwelling  Table K1 - Default  P4 Party wall - Roof (insulation at ceiling level)  Table K1 - Default  P4 Party wall - Roof (insulation at ceiling level)  W/m²K	Independently assess	sed E12 Gal	ble (insulation at cei	ling level)		12.27	0.077	No	CBA-310		
external area)  Table K1 - Default E25 Staggered party wall between dwellings 10.14 0.120 No  Table K1 - Default P1 Party wall - Ground floor 6.71 0.160 No  Table K1 - Default P2 Party wall - Intermediate floor within a 6.71 0.000 No  dwelling  Table K1 - Default P4 Party wall - Roof (insulation at ceiling level) 6.71 0.240 No  Y-value 0.065 W/m²K	Independently assess	sed E16 Co	rner (normal)			30.42	0.051	No	CBA-316		
Table K1 - Default E25 Staggered party wall between dwellings 10.14 0.120 No Table K1 - Default P1 Party wall - Ground floor 6.71 0.160 No Table K1 - Default P2 Party wall - Intermediate floor within a 6.71 0.000 No dwelling Table K1 - Default P4 Party wall - Roof (insulation at ceiling level) 6.71 0.240 No  Y-value 0.065 W/m²K	Table K1 - Approved		*	rnal area greatei	r than	10.14	-0.090	No	ACD		
Table K1 - Default P2 Party wall - Intermediate floor within a 6.71 0.000 No dwelling  Table K1 - Default P4 Party wall - Roof (insulation at ceiling level) 6.71 0.240 No  Y-value 0.065 W/m²K	Table K1 - Default		,	etween dwelling	S	10.14	0.120	No			
Table K1 - Default P4 Party wall - Roof (insulation at ceiling level) 6.71 0.240 No  Y-value 0.065 W/m²K	Table K1 - Default	P1 Part	y wall - Ground floo	r		6.71	0.160	No			
Table K1 - Default P4 Party wall - Roof (insulation at ceiling level) 6.71 0.240 No  Y-value 0.065 W/m²K	Table K1 - Default			e floor within a		6.71	0.000	No			
	Table K1 - Default		•	tion at ceiling lev	vel)	6.71	0.240	No			
18.0 Pressure Testing Yes	Y-value		0.065				W/m²K				
	18.0 Pressure Testing		Yes								





Designed AP		5.	75			m³/(h.m²) @ 50 Pa	
Property Tes							
As Built AP <sub>50</sub>	)					m <sup>3</sup> /(h.m <sup>2</sup> ) @ 50 Pa	
19.0 Mechanica	l Ventilation						
Summer Ove	erheating						
Window	s open in hot weat	her	Windows h	alf open			
Cross ve	ntilation possible		Yes				
Night Ve	ntilation		No				
Air chan	ge rate		4.00				
Mechanical	Ventilation						
Mechanic	al Ventilation System	Present	Yes				
Approve	d Installation		No				
Mechani	ical Ventilation dat	а Туре	Database				
Туре			Mechanical decentralise	extract ventila	tion -		
MV Refe	rence Number		500425				
Duct Typ	oe e		Rigid			<del></del>	
10.1 Machania	l extract ventilatio	n Decemb	ualiaa d				
SFP		Count	ranseu				
	Туре						
0.09	Through Wall	1					
0.09	Fan Kitchen Through Wall	1					
0.09	Fan Other Wet	1					
	Room						
0.11		1					
	Other Wet Room						
20.0 Fans, Open	Fireplaces, Flues		MHS	SHS	Other	Total	
Number of C	`himnevs		0	3H3	Other 0	0	
Number of o			0		0	0	
Number of i	ntermittent fans					0	
	assive vents					0	
Number of f	lueless gas fires					0	
21.0 Fixed Cooli	ng System	N	0				
22.0 Lighting							
Internal							
Total nu	mber of light fitting	gs 12	)			7	
	mber of L.E.L. fittin		)			Ī	
	age of L.E.L. fittings		00.00				
External						<b>_</b>	
	lights fitted	Ye	15			7	
	d motion sensor	Ye					
23.0 Electricity	「ariff	Sta	andard				
24.0 Main Heati	ng 1	Da	atabase				
Description		Sy	stem				
Percentage of	of Heat	10	00			%	
Database Re	f. No.	18	3403			7	





25.0 Main Heating 2	None
Flow Temperature	Normal (> 45°C)
Heat Emitter	Radiators
Is MHS Pumped	Pump in heated space
Fan Assisted Flue	Yes
Flue Type	Balanced
Sap Code	2110
Delayed Start Stat	No
PCDF Controls	0
Controls	CBI Time and temperature zone control
In Summer	80.1
In Winter	90.8
SAP Code	102
Main Heating	BGB
Fuel Type	Mains gas

None	
HWP From main heating 1	
Main Heating 1	
No	
Yes	
901	
Hot Water Cylinder	
Yes	
Yes	
Yes	
Measured Loss	
180.00	L
1.31	kWh/day
	HWP From main heating 1  Main Heating 1  No  No  No  No  No  Yes  901  Hot Water Cylinder  Yes  Yes  Yes  Yes  Measured Loss  180.00

### 31.0 Thermal Store Recommendations

Lower cost measures

None

Further measures to achieve even higher standards

None





Typical Cost

£4,000 - £6,000

£5,000 - £8,000

Typical Cost Typica

Solar photovoltaic panels, 2.5 kWp

Solar water heating

Typical savings per year £42 Typical savings per year

£310

Ratings after improvement

SAP rating Environmental Impact

B 85

Ratings after improvement

SAP rating Environmental Impact

A 95



#### **ASSESSMENT NOTES**

### **Calculation Type: New Build (As Designed)**



Property Reference	19037 Plot 049	19037 Plot 049				21/04/2019	
Assessment Reference	49	49 Prop Type Ref					
Property	49, The Paddocks, Green	Man Road, Na	venby, Lincoln, LN	5			
SAP Rating		83 B	DER	18.38	TER	18.40	
Environmental		85 B	% DER <ter< th=""><th></th><th>0.08</th><th></th></ter<>		0.08		
CO₂ Emissions (t/yo	ear)	1.50	DFEE	50.83	50.83 TFEE 56.91		
General Requireme	ents Compliance	Pass	% DFEE <tfee< th=""><th></th><th>10.67</th><th></th></tfee<>		10.67		
Assessor Details	Mr. Robert Atherton, Low Ca robert@lowcarbonbox.co.uk		ted, Tel: 07540977	7134, Assessor ID F291-0001			
Client							

ASSESSMENT NOTES - Last time updated on: 21.04.2019



#### **U-VALUE CALCULATOR REPORT**



Property Reference	19037 Plot 049				Issued on Date	21/04/2019	
Assessment Reference	49			Prop Type Ref	Helmsley semi		
Project	49, The Paddocks, Green	Man Road, Na	venby, Lincoli	ı, LN5			
Calculation Type	New Build (As Designed)						
SAP Rating		83 B	DER	18.38	TER	18.40	
Environmental		85 B	% DER <ter< th=""><th></th><th colspan="3">0.08</th></ter<>		0.08		
CO <sub>2</sub> Emissions (t/year)		1.50	DFEE	50.83	TFEE	56.91	
General Requirements	<b>Compliance</b>	Pass	% DFEE <tfe< th=""><th>E</th><th>10.67</th><th></th></tfe<>	E	10.67		
	. Robert Atherton, Low Carl pert@lowcarbonbox.co.uk	ed, Tel: 07540	977134,	Assessor ID	F291-0001		
Client							

#### **Building Elements**

#### Floor 000001 - Floor - b&b

Floor Type: Suspended Floor

Area = 44.93 m<sup>2</sup>, Perimeter = 22.85 m, Wall thickness = 300.00 mm, Soil: Clay

Depth of underfloor space below ground:0.200 m Floor wind shielding: Average (suburban)

Floor height above ground:h = 0.000 m

U-value of walls above ground:Uw = 1.500 m

Ventilation openings per perimeter length:e = 0.0015 %

Mean wind speed:v = 5.000 m/s

Resistance on solum:Rg = 0.000 m<sup>2</sup>K/W

Layer	Description	Thickness (mm)	Conductivity (W/m <sup>2</sup> K)	Resistance (m <sup>2</sup> K/W)	Fraction (%)
Ext surface				0.1700	
Layer 1	AAC (600 kg/m3)/ concrete				
	Main construction	100	0.1800	0.5556	86.30
	Main construction	100	1.3500	0.0741	13.70
Layer 2	Jabfloor 100				
	Main construction  Corrections - Air Gap: Level 1, Fasteners: None or plastic	150	0.0360	4.1667	100.00
Layer 3	Screed				
	Main construction	75	1.1500	0.0652	100.00
Int surface				0.1700	

Total resistance: Upper limit =  $5.056 \text{ m}^2 \text{ K/W}$  Lower limit =  $4.866 \text{ m}^2 \text{ K/W}$  Average =  $4.961 \text{ m}^2 \text{ K/W}$ 

Total correction =  $0.0071 \text{ m}^2 \text{ K/W}$  U-value (unrounded) =  $0.16 \text{ W/m}^2 \text{ K}$ 

Unheated space: None

Total thickness: 325 mm U-value: 0.16 W/m² K Kappa: n/a



#### THERMAL BRIDGING

### **Calculation Type: New Build (As Designed)**



<b>Property Reference</b>	19037 Plot 049	19037 Plot 049				21/04/2019	
Assessment	49		Prop Type Ref	Helmsley semi			
Reference Property	49, The Paddocks, Green	Man Road, Na	venby, Lincoli	n, LN5			
SAP Rating		83 B	DER	18.38	TER	18.40	
Environmental		85 B	% DER <ter< th=""><th></th><th colspan="3">0.08</th></ter<>		0.08		
CO <sub>2</sub> Emissions (t/yea	ar)	1.50	DFEE	50.83	TFEE	56.91	
General Requiremen	nts Compliance	Pass	% DFEE <tfe< th=""><th>E</th><th>10.67</th><th></th></tfe<>	E	10.67		
	Mr. Robert Atherton, Low Ca robert@lowcarbonbox.co.uk		ted, Tel: 07540	Assessor ID F291-0001			
Client							

	Junction detail	Source Type	Psi (W/mK)	Length (m)	Result	Reference
External wall	E1 Steel lintel with perforated steel base plate	Independently assessed	0.358	12.92	4.63	CBA-312
External wall	E3 Sill	Independently assessed	0.020	10.33	0.21	CBA-314
External wall	E4 Jamb	Independently assessed	0.016	31.65	0.51	CBA-315
External wall	E5 Ground floor (normal)	Independently assessed	0.094	22.85	2.15	CBA-301
External wall	E6 Intermediate floor within a dwelling	Independently assessed	0.000	22.85	0.00	CBA-303
External wall	E10 Eaves (insulation at ceiling level)	Independently assessed	0.036	10.58	0.38	Plasmor
External wall	E12 Gable (insulation at ceiling level)	Independently assessed	0.077	12.27	0.94	CBA-310
External wall	E16 Corner (normal)	Independently assessed	0.051	30.42	1.55	CBA-316
External wall	E17 Corner (inverted – internal area greater than external area)	Table K1 - Approved	-0.090	10.14	-0.91	ACD
External wall	E25 Staggered party wall between dwellings	Table K1 - Default	0.120	10.14	1.22	
Party wall	P1 Party wall - Ground floor	Table K1 - Default	0.160	6.71	1.07	
Party wall	P2 Party wall - Intermediate floor within a dwelling	Table K1 - Default	0.000	6.71	0.00	
Party wall	P4 Party wall - Roof (insulation at ceiling level)	Table K1 - Default	0.240	6.71	1.61	

Total: 13.35 W/mK: Y-Value: 0.065 W/m<sup>2</sup>K:

