

# Release News 2019.00 TRUCKS



## Release News TRUCKS 2019.00


2019.00 Updated vehicle database. A total of 12 brands are updated between the years 1998 to 2018.

### Updated brands are:

EvoBus Chassis, Generic Bus Systems, Iveco Bus, Iveco Trucks, MAN, Mercedes bus / Setra, Mercedes Truck, Optare, Plaxton, Renault Trucks, Solaris and VDL Bus & Coach.

More detailed information about the updated models and new adjustment features in 2019.00 is presented below.

## GUIDE



### Brand


Model	2004-2007	Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service
Adjustments	2004-2006	●	●	●	●			●	●	●
Programmings and tests	2006-2007								●	

Brands and Models are listed as in the CARS and TRUCKS software.

Year range in model includes a complete range for all systems with new or updated functionality.

The OBD functions e.g. Adjustments and programmings that are listed, are new or updated for the marked system.

Systems with markers are new or updated with read/erase fault codes, real time data and/or activations.



EvoBus Chassis

O580 Travego euro VI	2013-2017		•	•	•					•					
Tourismo euro VI	2014-2017		•							•					
BR 500 euro VI	2013-2017		•	•	•					•					
BR 400 euro VI	2013-2016									•					
Capacity euro VI	2014-2017					•				•					
Integro euro VI	2014-2016		•							•					
OC500 euro VI	2014-2017			•						•					
O530 Citaro euro VI	2013-2016									•					
Citaro II	2017				•	•				•					
Intouro euro VI	2014-2017		•							•					



Generic Bus Systems

16-pin J1962 diagnostic socket	All years									•					
9-pin Bus D-sub diagnostic socket	All years									•					
All supported systems	All years									•					



Iveco Bus

Euromidi	2014-2017	•	•	•	•	•	•	•	•						•
Accelerated clutch adaption	2017					•									
AdBlue dosing valve check	2017	•													
AdBlue dosing leakage check	2017	•													
AdBlue dosing pump check	2017	•													
AdBlue dosing valve	2017	•													
Additional fan	2017				•										
Air Suspension activation	2017														•
Air suspension calibration	2017														•
Bleed clutch actuator	2017					•									
Bleed clutch actuator (fast)	2017					•									
Bleed gearbox actuator	2017					•									
Bleed hydraulic pump	2017					•									
Calibration camera	2017									•					
Calibration Data	2017									•					
Calibration radar	2017									•					





Engine  
 Brake  
 Instrument  
 AC  
 Gearbox  
 Immobiliser  
 Restraints  
 Multifunction  
 Service  
 EV  
 Suspension  
 TPMS

Particle filter regeneration	2017	●																		
Particle filter replacement	2017	●																		
Rail pressure control valve replacement	2017	●																		
Rail pressure sensor replacement	2017	●																		
Readout of the basic data	2017	●																		
Replacement of engine crankcase pressure sensor	2017	●																		
Replacing the NOX sensor downstream of the catalytic converter	2017	●																		
Replacing the NOX sensor upstream of the oxidising catalyst	2017	●																		
Reset fault code 124 after replacement of clutch	2014-2017					●														
Steering angle calibration	2017		●																	
System test while operating	2014-2017					●														
Transmission actuator number	2014-2017					●														
Transmission actuator part list number	2014-2017					●														
Transmission parts list	2014-2017					●														
Transmission Serial number	2014-2017					●														
Trip information 1	2017	●																		
Trip information 2	2017	●																		
Write VIN	2014-2017					●														

Urbanway	2014-2017	●	●			●	●		●										●	
AdBlue dosing valve check	2017	●																		
AdBlue dosing leakage check	2017	●																		
AdBlue dosing pump check	2017	●																		
AdBlue dosing valve	2017	●																		
Calibration level sensors	2017																		●	
Change differential pressure sensor	2017	●																		
Compression test	2017	●																		
Cylinder deactivation	2017	●																		
Injector code programming	2017	●																		
Lateral acceleration sensor calibration	2017		●																	
Level sensor test	2017																		●	
Particle filter regeneration	2017	●																		
Particle filter replacement	2017	●																		
Rail pressure control valve replacement	2017	●																		
Rail pressure sensor replacement	2017	●																		
Readout of the basic data	2017	●																		
Replacement of engine crankcase pressure sensor	2017	●																		
Replacing the NOX sensor downstream of the catalytic converter	2017	●																		
Replacing the NOX sensor upstream of the oxidising catalyst	2017	●																		
Solenoid valves test	2017					●														
Steering angle calibration	2017		●																	
Trip information 1	2017	●																		
Trip information 2	2017	●																		

Minibus	2014-2017															●				
Deactivate service alert system	2014-2017															●				
Read service parameters	2014-2017															●				









		Engine	Brake	Instrument	AC	Gearbox	Immobiliser	Restraints	Multifunction	Service	EV	Suspension	TPMS
ECS system status	2017-2018											●	
Electronic controlled cooling fan test	2017-2018	●											
Engine brake test with the engine switched off	2017-2018	●											
Engine brake test with the engine switched on	2017-2018	●											
Engine protection data	2017-2018	●											
Engine torque against engine speed	2017-2018	●											
Foot brake valve, backup	2017-2018		●										
Forward looking sensor	2017-2018								●				
Fuel consumption data	2017-2018	●											
Function test of parking heater	2017-2018								●				
Gears, test	2017-2018					●							
Gearshift cylinder 1/reverse gear, test	2017-2018					●							
Gearshift cylinder 2/3, test	2017-2018					●							
Injector coding	2017-2018	●											
Injector function	2017-2018	●											
Instrument cluster, gauge test	2017-2018			●									
Instrument cluster, symbols	2017-2018			●									
Lane position camera	2017-2018								●				
Learning of active steering, front axle	2017-2018								●				
Level sensor test	2017-2018											●	
Manual regeneration of diesel particulate filter	2017-2018	●											
Modulator test	2017-2018		●										
Oil pressure test during engine start	2017-2018	●											
Parking heater, reset of all parameters	2017-2018									●			
Pneumatic system, test	2017-2018								●				
Pressure sensor test	2017-2018											●	
PWM valves clutch, test	2017-2018					●							
Rainsensor	2017-2018								●				
Range cylinder, test	2017-2018					●							
Read service parameters	2017-2018									●			
Rear axle steering calibration	2017-2018		●						●				
Rear axle steering parameters	2017-2018		●										
Reinitialize the learned parameters, EBS	2017-2018									●			
Reset of adaptive aftertreatment hydrocarbon	2017-2018									●			
Reset of ash and soot level	2017-2018									●			
Reset of battery parameters	2017-2018									●			
Reset of battery voltage sensor	2017-2018									●			
Reset of Burner motor, parking heater	2017-2018									●			
Reset of coolant pump	2017-2018									●			
Reset of EGR cooler	2017-2018									●			
Reset of EGR differential pressure sensor	2017-2018									●			
Reset of Fuel dosing pump, parking heater	2017-2018									●			
Reset of Glow plug, parking heater	2017-2018									●			
Reset of Heating fan, parking heater	2017-2018									●			
Reset of injector	2017-2018									●			
Reset of NOx sensor	2017-2018									●			
Reset of SCR system	2017-2018									●			
Reset of service message	2017-2018									●			
Reset of temperature sensor EGR	2017-2018									●			
Reset of Water pump, parking heater	2017-2018									●			









