

hpi check Results

VANWISE GROUP

HPI Check Results - 14/01/2021 16:22:22









Registration (VRM)

VIN/Chassis Number

YELLOW MERCEDES-BENZ SPRINTER 316 CDI


LN69NWS

WDB9076332P136714

Vehicle ID  Clear	MOT Details Not Checked	Stolen  Clear	Finance  Clear	Security Watch  Clear	Insurance Write Off (Damage)  Clear
Insurance Write Off (Theft)  Clear	Condition Inspected  Clear	Plate Transfer  Clear	Safety Recall Data Not Checked	V5 Check Not Checked	NMR CLICK TO ADD + Not Checked

FOR INTERNAL USE ONLY

Restrictions apply to the publication of certain DVLA data. HPI Certificates designed for display can be emailed to you. Please call us on 0113 222 2000 if you need any assistance with our services.

 Vehicle ID			
Make	MERCEDES-BENZ	Year of Manufacture	2019
Model	SPRINTER 316 CDI	Number of Former Keepers	0
Engine Size	2143cc	Start Date of Current Keeper	30/09/2019
Colour	YELLOW	Previous Colour	
Fuel	Diesel	Date Colour Changed	
Doorplan	Insulated/Refrigerated Van	Wheelplan	2 Axle Rigid Body
Engine Number	65195835142029	Gross Vehicle Weight	3500 (KG)
Transmission	4 Speed Manual Diesel	Exported	No
Date of 1st Registration in the UK	30/09/2019	Scrap Marker	No
CO2 Rating	207 (g/km)		