

**TOWNSHIP OF RIDEAU**  
**BUILDING DEPARTMENT**  
**BUILDING INSPECTION REPORT**

PERMIT # 1855

OWNER'S NAME: Dale Kirkpatrick

DATE OF REQUEST: 1

BUILDER NAME: \_\_\_\_\_

DATE FOR INSPECTION: Dec 6/93

PHONE: \_\_\_\_\_

TIME FOR INSPECTION: \_\_\_\_\_

LOCATION OF Lot 32 M-244

DATE OF INSPECTION: \_\_\_\_\_

INSPECTION: 7645 Settlers Way

TIME OF INSPECTION: \_\_\_\_\_

**TYPE OF INSPECTION:**

Foundation \_\_\_\_\_

Sewer Connection \_\_\_\_\_

Framing and Rough Plumbing \_\_\_\_\_

Occupancy \_\_\_\_\_

Insulation \_\_\_\_\_

Final wood stove ☒

Others \_\_\_\_\_

The above work has PASSED \_\_\_\_\_ / FAILED \_\_\_\_\_ Inspection.

**COMMENTS:**

\_\_\_\_\_ Work may proceed

\_\_\_\_\_ Work may not proceed.  
Rectify deficiencies and call for  
another appointment

\_\_\_\_\_ Work may proceed subject to  
other required approvals

\_\_\_\_\_ Work not ready for inspection,  
call for another appointment  
when ready

\_\_\_\_\_ Work may proceed when  
deficiencies have been rectified


\_\_\_\_\_ Please submit OLS elevation  
certificate

\_\_\_\_\_ Please submit O.L.S.  
building location survey

**DEFICIENCIES AND OTHER COMMENTS:**

Wood Stove & chimney installation

Ok



INSPECTOR

WOOD BURNING STOVE QUESTIONNAIRE

BROKER: Sm. Hill Insurance

NAME OF INSURED: Dale Kirkpatrick

POLICY NO.: 9306072

APPLICABLE TO LOCATION NO.: 1



**Economical**  
Mutual Insurance Company

333 Preston Street, Suite 400  
Commerce Plaza  
Ottawa, Ontario  
K1S 5N4  
Main: (613) 567-7060  
Claims: (613) 567-7065  
Fax: (613) 567-6981

C.F. Phipps  
Manager

1. IS THE UNIT ULC OR CSA APPROVED? Yes
2. WAS THE UNIT PROFESSIONALLY INSTALLED? Chimney was
3. IS THE UNIT ON A NON-COMBUSTIBLE PAD WHICH EXTENDS AT LEAST 18" ON LOADING SIDE AND 12" ON THE OTHER SIDES? Yes
4. a) DOES THE UNIT HAVE MORE THAN THREE FEET CLEARANCE ON ALL SIDES WITH PROPER SHEILDING? No  
b) WHAT TYPE OF SHEILDING WAS USED? built on the stove  
c) IF LESS THAN THREE FEET AND SHEILDDED, WHAT ARE THE CLEARANCES? 18" from chimney to wall  
IS THERE AT LEAST A 1" AIRSPACE BETWEEN THE WALL AND SHEILDING? N/A
5. a) DOES THE UNIT HAVE ITS OWN SEPERATE CHIMNEY DESIGNED FOR SOLID FUELS? Yes  
b) IF NOT, IS STOVE FLUED INTO CHIMNEY BELOW FURNACE? \_\_\_\_\_
6. IF THE DUCTS PASS THROUGH WALLS CONSTRUCTED OF MATERIAL OTHER THAN BRICK OR MORTAR, ARE THIMBLES USED? N/A
7. HOW MANY STOVE CORDS OF WOOD ARE USED PER YEAR? 2 cords of wood
8. ARE ASHES PLACED IN A METAL CONTAINER? Yes
9. HOW MANY TIMES A YEAR IS THE CHIMNEY CLEANED? 1-2
10. IS THE UNIT USED FOR 50% OR MORE OF THE HEATING, DURING THE HEATING SEASON? No
11. HAS THE INSTALLATION BEEN INSPECTED AND APPROVED BY:  
a) FIRE DEPARTMENT \_\_\_\_\_ b) BUILDING INSPECTOR ✓  
DATE OF INSPECTION Dec '93  
NAME OF INSPECTOR (IF AVAILABLE) Jack Moffatt  
PLEASE FORWARD A COPY OF INSPECTION IF POSSIBLE.
12. PLEASE ATTACH A PHOTOGRAPH OF THE HEATING UNIT. N/A available

SIGNATURE OF INSURED Dale Kirkpatrick

TELEPHONE NUMBERS (613) 258-4367

DATE Dec 12 '93

Home•Business•Auto  
Established 1871  
Head Office: Waterloo, Ontario