

Picture Works, Nottingham | Fire safety situation report

Update 31 July 2020

As previously mentioned, the works are covered by the building warranty. The previously instructed project managers did not have adequate indemnity insurance and new project managers have now been instructed who are putting together their proposal to address the render system at the building.