

## **Picture Works, Nottingham | Fire safety situation report**

### **Update 30 September 2020**

The landlord has made an application to the Government's Building Safety Fund in respect of the need for replacement of the render on the exterior of the building. A project manager has been appointed with a fire engineering company to specify the render remedial work required.